


39. 용흥고가(B58)



위치	1(1SPAN-1)	선별	T2	위치	TCL
내용	균열	Cw= 0.3/0.2			



위치	2(1SPAN-2)	선별	T2	위치	TCL
내용	균열	Cw= 0.3/5.5			



위치	31(6SPAN-1)	선별	T1	위치	TCL
내용	경계부 균열	Cw= 0.3/2.3			



위치	31(6SPAN-1)	선별	T1	위치	TCL
내용	균열	Cw= 0.1/2.3			



위치	28(5SPAN-3)	선별	T1	위치	TCL
내용	균열	Cw= 0.2/0.4			



위치	19(3SPAN-4)	선별	T2	위치	TCL
내용	균열	Cw= 0.2/2.3			