

40. 용흥고가_토공노반(G86)



위치	STA. 161.569-579	선별	T2	위치	TCL
내용	균열	Cw= 0.3/2.3			



위치	STA. 161.599-609	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	STA. 161.609-619	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	STA. 161.619-629	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	STA. 161.619-629	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	STA. 161.619-629	선별	T2	위치	TCL
내용	침목도상분리	1EA			




위치	STA. 161.649-659	선별	T2	위치	TCL
내용	침목도상분리	1EA			



위치	STA. 161.669-679	선별	T2	위치	TCL
내용	파손	A= 0.6x0.8			




위치	STA. 161.609-619	선별	T1	위치	TCL
내용	침목파손	A= 0.1x0.1			



위치	STA. 161.809-819	선별	T2	위치	TCL
내용	침목파손	A= 0.1x0.1			





위치	STA. 161.939-949	선별	T2	위치	TCL
내용	경계부 균열	Cw= 0.1/2.3			




위치	STA. 162.079-089	선별	T2	위치	HSB
내용	파손	A= 0.2x0.4			



위치	STA. 162.199-209	선별	T1	위치	TCL	위치	STA. 162.279-289	선별	T2	위치	TCL
내용	경계부 균열		Cw= 0.1/2.3	내용	박락		A= 0.1x4.0				



위치	STA. 162.309-319	선별	T1	위치	TCL	위치	STA. 162.309-319	선별	T2	위치	TCL
내용	균열		Cw= 0.3/0.4	내용	균열		Cw= 0.2/0.4				



위치	STA. 162.329-339	선별	T2	위치	채움	위치	STA. 162.349-354	선별	T2	위치	TCL
내용	박리		A= 0.1x4.0	내용	침묵도상분리		1EA				