



44. 황룡1교 토공노반(G88)

																							
위치	STA. 164.381-391			선별	T1	위치	TCL			위치	STA. 164.411-421			선별	T1	위치	TCL						
내용	파손			A= 0.1X0.1						내용	균열			Cw= 0.1/1.1									
																							
위치	STA. 164.411-421			선별	T1	위치	TCL			위치	STA. 164.411-421			선별	T2	위치	TCL						
내용	균열			Cw= 0.1/0.8						내용	균열			Cw= 0.1/1.1									
																							
위치	STA. 164.421-431			선별	T1	위치	채움			위치	STA. 164.421-431			선별	T1	위치	채움						
내용	균열			Cw= 1.0/3.5						내용	균열			Cw= 1.0/2.0									




위치	STA. 164.481-491	선별	T2	위치	TCL
내용	균열	Cw=	0.1/0.4		



위치	STA. 164.481-491	선별	T2	위치	TCL
내용	균열	Cw=	0.2/2.0		



위치	STA. 164.481-491	선별	T2	위치	TCL
내용	균열	Cw=	0.1/0.1		



위치	STA. 164.481-491	선별	T2	위치	TCL
내용	균열	Cw=	0.1/0.1		





위치	STA. 164.511-521	선별	T1	위치	TCL
내용	균열	Cw=	0.1/1.0		



위치	STA. 164.511-521	선별	T2	위치	TCL
내용	균열	Cw=	0.1/0.9		



위치	STA. 164.591-601	선별	T2	위치	TCL	위치	STA. 164.591-601	선별	T2	위치	TCL
내용	균열		Cw= 0.2/0.9			내용	균열		Cw= 0.1/1.5		



위치	STA. 164.741-751	선별	T1	위치	TCL						
내용	파손		A= 0.2/0.2								

