


## 47. 와룡1터널 (U30)

---







|    |                  |    |             |    |     |
|----|------------------|----|-------------|----|-----|
| 위치 | STA. 166K556-566 | 선별 | T1          | 위치 | TCL |
| 내용 | 균열 (2EA)         |    | Cw= 0.2/0.4 |    |     |



|    |                  |    |             |    |    |
|----|------------------|----|-------------|----|----|
| 위치 | STA. 166K566-576 | 선별 |             | 위치 | 채움 |
| 내용 | 균열               |    | Cw= 0.2/1.5 |    |    |



|    |                  |    |            |    |     |
|----|------------------|----|------------|----|-----|
| 위치 | STA. 166K566-576 | 선별 | T2         | 위치 | HSB |
| 내용 | 파손               |    | A= 0.1x0.1 |    |     |



|    |                  |    |            |    |     |
|----|------------------|----|------------|----|-----|
| 위치 | STA. 166K566-576 | 선별 | T2         | 위치 | HSB |
| 내용 | 파손               |    | A= 0.4x0.5 |    |     |



|    |                  |    |             |    |    |
|----|------------------|----|-------------|----|----|
| 위치 | STA. 166K756-766 | 선별 |             | 위치 | 채움 |
| 내용 | 균열               |    | Cw= 0.3/1.5 |    |    |



|    |                  |    |             |    |    |
|----|------------------|----|-------------|----|----|
| 위치 | STA. 166K786-796 | 선별 |             | 위치 | 채움 |
| 내용 | 균열               |    | Cw= 0.3/1.5 |    |    |