



48. 와룡1터널 토공노반(G90)




위치	STA. 166K556-566	선별	T1	위치	TCL
내용	균열 (2EA)		Cw= 0.2/0.4		



위치	STA. 166K566-576	선별		위치	채움
내용	균열		Cw= 0.2/1.5		



위치	STA. 166K566-576	선별	T2	위치	HSB
내용	파손		A= 0.1x0.1		



위치	STA. 166K566-576	선별	T2	위치	HSB
내용	파손		A= 0.4x0.5		




위치	STA. 166K756-766	선별		위치	채움
내용	균열		Cw= 0.3/1.5		




위치	STA. 166K786-796	선별		위치	채움
내용	균열		Cw= 0.3/1.5		




위치	STA. 166K796-806	선별	T2	위치	HSB
내용	파손	A= 0.2x0.2			




위치	STA. 166K806-816	선별		위치	채움
내용	균열	Cw= 0.3/1.5			




위치	STA. 166K816-826	선별	T2	위치	TCL
내용	균열	Cw= 0.2/0.4			



위치	STA. 166K816-826	선별	T2	위치	TCL
내용	균열	Cw= 0.2/0.4			



위치	STA. 166K826-836	선별	T1	위치	TCL
내용	균열	Cw= 0.2/0.3			



위치	STA. 166K856-866	선별	T2	위치	TCL
내용	균열	Cw= 0.2/0.5			