





51. 와룡2터널 (U31)

																							
위치	STA. 169.553-563				선별	T1	위치	TCL				위치	STA. 169.513-523				선별	T1	위치	도상			
내용	균열				Cw= 0.3/0.4				내용	균열				Cw= 1.0/1.0									
																							
위치	STA. 169.503-513				선별	T2	위치	TCL				위치	STA. 169.493-503				선별	T1	위치	도상			
내용	균열				Cw= 0.3/1.0				내용	균열				Cw= 0.5/1.0									
																							
위치	STA. 169.483-493				선별	T1	위치	TCL				위치	STA. 169.483-493				선별	T1	위치	TCL			
내용	균열				Cw= 0.3/0.4				내용	균열				Cw= 0.3/0.1									

											
위치	STA. 169.473-483	선별	T1	위치	TCL	위치	STA. 169.423-433	선별	T1	위치	TCL
내용	균열		Cw= 0.3/0.4			내용	균열		Cw= 0.3/0.3		
											
위치	STA. 169.393-403	선별	T2	위치	도상	위치	STA. 169.393-403	선별	T1	위치	도상
내용	균열		Cw= 1.0/0.5			내용	균열		Cw= 1.0/0.5		
											
위치	STA. 169.363-373	선별	T2	위치	도상	위치	STA. 169.363-373	선별	T1	위치	도상
내용	균열		Cw= 0.6/1.0			내용	균열		Cw= 0.5/1.0		

