









59. 신통고가(B64)

																			
위치	STA. 172K385-393			선별	T1	위치	STA. 172K385-393			선별	T1	위치	TCL						
내용	경계부 균열			Cw= 0.1/2.3			내용	균열			Cw= 0.5/1.2								
																			
위치	STA. 172K401-409			선별	T2	위치	STA. 172K417-425			선별	T2	위치	TCL						
내용	균열			Cw= 0.2/0.4			내용	균열			Cw= 0.2/0.3								
																			
위치	STA. 172K425-433			선별	T2	위치	STA. 172K433-441			선별	T1	위치	TCL						
내용	균열			Cw= 0.2/0.5			내용	균열			Cw= 0.2/0.3								

																							
위치		STA. 172K433-441		선별		T1		위치		TCL		위치		STA. 172K433-441		선별		T1		위치		TCL	
내용		균열				Cw= 0.2/0.3						내용		균열				Cw= 0.2/0.3					
																							
위치		STA. 172K465-473		선별		T2		위치		TCL		위치		STA. 172K789-797		선별		T1		위치		TCL	
내용		균열				Cw= 0.2/0.4						내용		균열				Cw= 0.3/0.4					
																							
위치		STA. 172K813-821		선별		T1		위치		PCL		위치		STA. 172K821-829		선별		T1		위치		PCL	
내용		백태				A= 0.6x6.0						내용		백태				A= 0.3x10.0					