





62. 신흥터널 토공노반(G97)


											
위치	STA. 173K348-358	선별	T1	위치	HSB	위치	STA. 173K388-398	선별	T2	위치	TCL
내용	균열		Cw= 0.3/0.3			내용	균열		Cw= 0.2/0.4		
											
위치	STA. 173K508-518	선별	T1	위치	TCL	위치	STA. 173K518-528	선별	T2	위치	TCL
내용	균열		Cw= 0.2/0.3			내용	균열		Cw= 0.2/0.8		
											
위치	STA. 173K618-628	선별	T2	위치	TCL	위치	STA. 173K618-628	선별	T2	위치	TCL
내용	균열		Cw= 0.2/0.8			내용	백태		A= 0.1x0.2		




위치	STA. 173K628-638	선별	T2	위치	TCL
내용	균열		Cw= 0.3/0.4		



위치	STA. 173K638-648	선별	T2	위치	TCL
내용	균열		A= 0.1x0.2		




위치	STA. 173K638-648	선별	T2	위치	TCL
내용	백태		A= 0.1x0.2		





위치	STA. 173K678-688	선별	T1	위치	TCL
내용	균열		Cw= 0.2/0.8		



위치	STA. 173K678-688	선별	T1	위치	침목
내용	경계부 균열		Cw= 0.2/2.3		



위치	STA. 173K738-748	선별	T2	위치	TCL
내용	균열		Cw= 0.2/0.8		

											
위치	STA. 173K818-828	선별	T2	위치	침목	위치	STA. 173K918-928	선별	T1	위치	TCL
내용	경계부 균열		Cw= 0.2/2.3			내용	균열		Cw= 0.2/0.8		
											
위치	STA. 174K018-028	선별	T1	위치	TCL	위치		선별		위치	
내용	균열 (2EA)		Cw= 0.2/0.4			내용					
위치		선별		위치		위치		선별		위치	
내용				내용		내용					