








68. 장수고가 토공노반(G100)

																					
위치	STA. 177K017-027				선별	T1		위치	HSB		위치	STA. 177K017-027				선별	T1		위치	HSB	
내용	박리				A= 0.2x0.2				내용	균열				Cw= 0.5/0.4							
																					
위치	STA. 177K087-097				선별	T1		위치	HSB		위치	STA. 177K097-107				선별	T1		위치	HSB	
내용	충분리보수미흡				A= 0.2x7.0				내용	충분리보수미흡				A= 0.2x10.0							
																					
위치	STA. 177K107-117				선별	T2		위치	HSB		위치	STA. 177K167-177				선별	T2		위치	HSB	
내용	균열				Cw= 1.0/0.6				내용	균열				Cw= 0.5/0.6							

																							
위치	STA. 177K207-217				선별	T2		위치	HSB				위치	STA. 177K217-227				선별	T2		위치	HSB	
내용	균열				Cw= 1.0/0.6				내용	균열				Cw= 0.5/0.6									
																							
위치	STA. 178K037-047				선별	T2		위치	TCL				위치	STA. 178K307-317				선별	T1		위치	TCL	
내용	마감불량				A= 0.2x0.2				내용	균열				Cw= 0.2/0.4									
																							
위치	STA. 178K307-317				선별	T1		위치	TCL				위치	STA. 178K487-497				선별	T1		위치	TCL	
내용	침목 경계부 균열				Cw= 0.1/2.3				내용	균열				Cw= 0.2/0.4									

																							
위치	STA. 178K487-497				선별	T1		위치	TCL		위치	STA. 178K547-557				선별	T1		위치	TCL			
내용	침목 경계부 균열				Cw= 0.1/2.3				내용	침목파손				A= 0.1x0.1									
																							
위치	STA. 178K567-577				선별			위치	채움		위치					선별			위치				
내용	균열				Cw= 0.5/2.0				내용														
																							
위치					선별			위치			위치					선별			위치				
내용									내용														