


호남고속선 오송고가(T1)_15(1.386~1.394km, S5-5)



(아
0호)

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	구경	0.3	1.2		56				
2	파손	0.1	m	m	57				
3					58				
4					59				
5					60				
6					61				
7					62				
8					63				
9					64				
10					65				
11					66				
12					67				
13					68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행 사	영 역	영 역	영 역	사	인 지		단		
						과 업	인 지		분 야	인 지
	한국철도공사	2017년도 호남고속선 오송-광주승정간 편크리트캐도 점경영어	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 박 영	강 원 강 김 경 기 윤 석 기	영역				
						 0.220 (0.3m이하 : 폭식)	 0.420 (0.3m초과 0.5m이하 : 형식)	 0.620 (0.5m초과 1.0m이하 : 적석)		
									 1.020 (1.0m이상 : 분포식)	 한목도상문리
						 바리,바라,파손	 백태	 재료문리		
						 누수,슬관부	 지층이음문리,총문리			