



호남고속선 오송고가(T1)_42(1.760~1.774km, S13-9,S13-10)


$$\begin{pmatrix} \text{아} \\ \text{호} \end{pmatrix}$$

$$\begin{pmatrix} \text{아} \\ \text{아} \end{pmatrix}$$

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	강제부 균열	0.2	mm	0.5 m	56				
2	강제부 균열	0.2	mm	0.5 m	57				
3	균열	0.1	mm	0.3 m	58				
4	균열	0.1	mm	0.3 m	59				
5	균열	0.1	mm	0.3 m	60				
6	균열	0.1	mm	0.3 m	61				
7	균열	0.1	mm	0.4 m	62				
8	균열	0.1	mm	0.4 m	63				
9	균열	0.1	mm	0.4 m	64				
10	피손	0.2	m	0.1 m	65				
11	균열	0.1	mm	0.4 m	66				
12	균열	0.1	mm	0.4 m	67				
13	바닥	0.2	m	0.2 m	68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

[illegible]