



호남고속선 오송고가(T2)_2(1.210~1.226km, S1-3,S1-4)



연번	순상	목	연장	비고	연번	순상	목	연장	비고
1	균열	0.2 mm	0.6 m		56				
2	균열	0.2 mm	0.4 m		57				
3	균열	0.2 mm	0.4 m		58				
4	균열	0.2 mm	0.4 m		59				
5	균열	0.2 mm	0.4 m		60				
6	균열	0.2 mm	0.4 m		61				
7	균열	0.2 mm	0.4 m		62				
8	균열	0.2 mm	0.6 m		63				
9	균열	0.2 mm	0.4 m		64				
10	균열	0.2 mm	0.6 m		65				
11	균열	0.2 mm	0.4 m		66				
12	균열	0.2 mm	0.4 m		67				
13	균열	0.2 mm	0.6 m		68				
14	균열	0.2 mm	0.6 m		69				
15	균열	0.2 mm	0.6 m		70				
16	균열	0.2 mm	0.4 m		71				
17	균열	0.2 mm	0.6 m		72				
18	균열	0.2 mm	0.4 m		73				
19	균열	0.2 mm	0.4 m		74				
20	균열	0.1 mm	0.6 m		75				
21	균열	0.1 mm	0.6 m		76				
22	균열	0.2 mm	0.6 m		77				
23	균열	0.2 mm	0.6 m		78				
24	균열	0.2 mm	0.6 m		79				
25	균열	0.2 mm	0.6 m		80				
26	균열	0.1 mm	0.6 m		81				
27	균열	0.2 mm	0.6 m		82				
28	균열	0.1 mm	0.4 m		83				
29	균열	0.1 mm	0.4 m		84				
30	균열	0.1 mm	0.6 m		85				
31	균열	0.2 mm	0.6 m		86				
32	균열	0.1 mm	0.6 m		87				
33	균열	0.2 mm	0.6 m		88				
34	균열	0.2 mm	0.6 m		89				
35	균열	0.2 mm	0.6 m		90				
36	균열	0.2 mm	0.6 m		91				
37	균열	0.2 mm	0.6 m		92				
38	균열	0.2 mm	0.6 m		93				
39	균열	0.1 mm	0.6 m		94				
40	균열	0.2 mm	0.6 m		95				
41	균열	0.2 mm	0.6 m		96				
42	균열	0.2 mm	0.6 m		97				
43	균열	0.1 mm	0.4 m		98				
44	균열	0.1 mm	0.4 m		99				
45	균열	0.1 mm	0.4 m		100				
46	균열	0.2 mm	0.4 m		101				
47	균열	0.2 mm	0.6 m		102				
48	균열	0.2 mm	0.6 m		103				
49	균열	0.2 mm	0.6 m		104				
50	균열	0.2 mm	0.6 m		105				
51	균열	0.2 mm	0.6 m		106				
52	균열	0.2 mm	0.6 m		107				
53	균열	0.1 mm	0.6 m		108				
54	균열	0.1 mm	0.6 m		109				
55					110				

시	행	사	용	여	명	용	여	사	관				
									과 업 책 임 자	장 분 아 책 임 자			
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 코크리트케도 점검용역	(주)한국구조물안전연구원 (주)한국도로안전연구원 (제)한국건설품질연구원	이복영	김문강 김경기 한은석	용	〰〰〰 (0.3mm이하 : 흑색)	0.220	천문도상문리		제료문리		
								〰〰〰 (0.3mm초과 0.5mm이하 : 청색)	0.420	양산간열		철근노출	
								〰〰〰 (0.5mm초과 1.0mm이하 : 적색)	0.620	바리, 바락, 파손		누수 습윤 부	
								〰〰〰 (1.0mm이상 : 분홍색)	1.020	번대		시공이음문리, 종문리	