



호남고속선 오송고가(T2)\_72(2.143~2.157km, S21-3,S21-4)



| 구분 | 번호 | 손상 | 폭   | 연장 | 비고   | 구분  | 번호  | 손상 | 폭 | 연장 | 비고 |
|----|----|----|-----|----|------|-----|-----|----|---|----|----|
| 1  | 1  | 균열 | 0.1 | mm | 0.15 | m   | 56  |    |   |    |    |
|    | 2  | 균열 | 0.1 | mm | 0.5  | m   | 57  |    |   |    |    |
|    | 3  |    |     |    |      |     | 58  |    |   |    |    |
| 4  | 4  |    |     |    |      |     | 59  |    |   |    |    |
|    | 5  |    |     |    |      |     | 60  |    |   |    |    |
|    | 6  |    |     |    |      |     | 61  |    |   |    |    |
| 7  | 7  |    |     |    |      |     | 62  |    |   |    |    |
|    | 8  |    |     |    |      |     | 63  |    |   |    |    |
|    | 9  |    |     |    |      |     | 64  |    |   |    |    |
| 10 | 10 |    |     |    |      |     | 65  |    |   |    |    |
|    | 11 |    |     |    |      |     | 66  |    |   |    |    |
|    | 12 |    |     |    |      |     | 67  |    |   |    |    |
| 13 | 13 |    |     |    |      |     | 68  |    |   |    |    |
|    | 14 |    |     |    |      |     | 69  |    |   |    |    |
|    | 15 |    |     |    |      |     | 70  |    |   |    |    |
| 16 | 16 |    |     |    |      |     | 71  |    |   |    |    |
|    | 17 |    |     |    |      |     | 72  |    |   |    |    |
|    | 18 |    |     |    |      |     | 73  |    |   |    |    |
| 19 | 19 |    |     |    |      |     | 74  |    |   |    |    |
|    | 20 |    |     |    |      |     | 75  |    |   |    |    |
|    | 21 |    |     |    |      |     | 76  |    |   |    |    |
| 22 | 22 |    |     |    |      |     | 77  |    |   |    |    |
|    | 23 |    |     |    |      |     | 78  |    |   |    |    |
|    | 24 |    |     |    |      |     | 79  |    |   |    |    |
| 25 | 25 |    |     |    |      |     | 80  |    |   |    |    |
|    | 26 |    |     |    |      |     | 81  |    |   |    |    |
|    | 27 |    |     |    |      |     | 82  |    |   |    |    |
| 28 | 28 |    |     |    |      |     | 83  |    |   |    |    |
|    | 29 |    |     |    |      |     | 84  |    |   |    |    |
|    | 30 |    |     |    |      |     | 85  |    |   |    |    |
| 31 | 31 |    |     |    |      |     | 86  |    |   |    |    |
|    | 32 |    |     |    |      |     | 87  |    |   |    |    |
|    | 33 |    |     |    |      |     | 88  |    |   |    |    |
| 34 | 34 |    |     |    |      |     | 89  |    |   |    |    |
|    | 35 |    |     |    |      |     | 90  |    |   |    |    |
|    | 36 |    |     |    |      |     | 91  |    |   |    |    |
| 37 | 37 |    |     |    |      |     | 92  |    |   |    |    |
|    | 38 |    |     |    |      |     | 93  |    |   |    |    |
|    | 39 |    |     |    |      |     | 94  |    |   |    |    |
| 40 | 40 |    |     |    |      |     | 95  |    |   |    |    |
|    | 41 |    |     |    |      |     | 96  |    |   |    |    |
|    | 42 |    |     |    |      |     | 97  |    |   |    |    |
| 43 | 43 |    |     |    |      |     | 98  |    |   |    |    |
|    | 44 |    |     |    |      |     | 99  |    |   |    |    |
|    | 45 |    |     |    |      |     | 100 |    |   |    |    |
| 46 | 46 |    |     |    |      |     | 101 |    |   |    |    |
|    | 47 |    |     |    |      |     | 102 |    |   |    |    |
|    | 48 |    |     |    |      |     | 103 |    |   |    |    |
| 49 | 49 |    |     |    |      |     | 104 |    |   |    |    |
|    | 50 |    |     |    |      |     | 105 |    |   |    |    |
|    | 51 |    |     |    |      |     | 106 |    |   |    |    |
| 52 | 52 |    |     |    |      |     | 107 |    |   |    |    |
|    | 53 |    |     |    |      |     | 108 |    |   |    |    |
|    | 54 |    |     |    |      |     | 109 |    |   |    |    |
| 55 |    |    |     |    |      | 110 |     |    |   |    |    |