



호남고속선 오송고가(T2)_108(2.638~2.652km, S27-5,S27-6)



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.2 mm	0.8 m	m		56				
2	균열 0.1 mm	0.4 m	m		57				
3	균열 0.1 mm	0.6 m	m		58				
4	균열 0.2 mm	0.6 m	m		59				
5	균열 0.2 mm	0.6 m	m		60				
6	파손 0.2 m	0.1 m	m		61				
7	균열 0.1 mm	0.8 m	m		62				
8	균열 0.1 mm	0.4 m	m		63				
9	균열 0.1 mm	0.6 m	m		64				
10	균열 0.2 mm	0.6 m	m		65				
11	균열 0.2 mm	0.6 m	m		66				
12	균열 0.2 mm	0.6 m	m		67				
13	균열 0.2 mm	0.6 m	m		68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				