


호남고속선 각산터널_95(10.020~10.030km, S95)

10K020

10K030



연번	손상	폭	연장	비고	연번	손상	폭	연장	비고
1	균열	0.2	mm	0.40	m	56			
2	균열	0.2	mm	0.60	m	57			
3	균열	0.2	mm	0.40	m	58			
4	균열	0.2	mm	0.30	m	59			
5	균열	0.2	mm	0.30	m	60			
6	균열	0.2	mm	0.40	m	61			
7	균열	0.2	mm	0.90	m	62			
8	균열	0.2	mm	0.30	m	63			
9	균열	0.2	mm	0.40	m	64			
10	균열	0.5	mm	2.00	m	65			
11	균열	0.1	mm	0.40	m	66			
12	균열	0.1	mm	0.40	m	67			
13	균열	0.1	mm	0.40	m	68			
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

[illegible]