


호남고속선 부용터널_141(14.240~14.250km, S139)



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.2 mm	0.6 m		56				
2	균열	0.2 mm	0.3 m		57				
3	균열	0.2 mm	0.3 m		58				
4	균열	0.2 mm	0.3 m		59				
5	균열	0.2 mm	0.4 m		60				
6	균열	0.1 mm	0.4 m		61				
7	균열	0.1 mm	0.4 m		62				
8	균열	0.1 mm	0.5 m		63				
9	균열	0.2 mm	0.3 m		64				
10	균열	0.2 mm	0.3 m		65				
11	균열	0.1 mm	0.3 m		66				
12	균열	0.2 mm	0.3 m		67				
13	균열	0.2 mm	0.3 m		68				
14	균열	0.1 mm	0.3 m		69				
15	균열	0.1 mm	0.3 m		70				
16	균열	0.2 mm	0.3 m		71				
17	균열	0.1 mm	0.3 m		72				
18	균열	0.2 mm	0.4 m		73				
19	균열	0.2 mm	0.4 m		74				
20	균열	0.2 mm	0.3 m		75				
21	균열	0.2 mm	0.3 m		76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

 한국철도공사 KOREA RAILROAD	시행사	공역명	공역소재지	주요사업내용	구분	비고	
				(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	개업연월일	정기점검	
				이북영	관리부서	관리인명	
				간호강 김경희 윤석기	구분	비고	
					0.2220 (0.3m이하 : 열차)	한탄도안분기점	
				0.4820 (0.3m초과 0.5m이하 : 경차)	양산		
				0.6920 (0.5m초과 1.0m미만 : 경차)	바리, 바리, 파손	누수수문부	
				1.0220 (1.0m이상 : 통행)	변대	시공이음판리, 통행리	