

호남고속선 부산고가 _24(21.826~21.834km, S4-4)

[illegible]

연번	순차	폭	연장	비고	연번	순차	폭	연장	비고
1	균열	0.1 mm	0.4 m		56				
2	경계부 균열	0.2 mm	0.6 m		57				
3	균열	0.1 mm	0.3 m		58				
4	균열	0.1 mm	0.4 m		59				
5	균열	0.1 mm	0.4 m		60				
6	균열	0.1 mm	0.4 m		61				
7	균열	0.1 mm	0.4 m		62				
8	경계부 균열	0.1 mm	0.3 m		63				
9	균열	0.2 mm	0.6 m		64				
10	균열	0.1 mm	0.3 m		65				
11	균열	0.1 mm	0.4 m		66				
12	경계부 균열	0.2 mm	0.6 m		67				
13	경계부 균열	0.2 mm	0.9 m		68				
14	균열	0.1 mm	0.3 m		69				
15	경계부 균열	0.2 mm	0.9 m		70				
16	경계부 균열	0.2 mm	0.6 m		71				
17	경계부 균열	0.1 mm	0.3 m		72				
18	경계부 균열	0.2 mm	0.9 m		73				
19	균열	0.2 mm	0.6 m		74				
20	균열	0.1 mm	0.3 m		75				
21	균열	0.2 mm	0.3 m		76				
22	균열	0.1 mm	0.3 m		77				
23	균열	0.1 mm	0.3 m		78				
24	균열	0.1 mm	0.7 m		79				
25	균열	0.1 mm	0.7 m		80				
26	균열	0.1 mm	0.3 m		81				
27	균열	0.1 mm	0.3 m		82				
28	균열	0.2 mm	0.3 m		83				
29	균열	0.1 mm	0.7 m		84				
30	균열	0.1 mm	0.7 m		85				
31	균열	0.1 mm	0.7 m		86				
32	균열	0.1 mm	0.3 m		87				
33	균열	0.1 mm	0.3 m		88				
34	균열	0.1 mm	0.4 m		89				
35	균열	0.1 mm	0.4 m		90				
36	균열	0.1 mm	0.4 m		91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행	사	용	여	용	여	사	간									
								과	인	장	아	지					
KORAIL KOREA RAILROAD	한국철도공사	2017년도	호남고속선	오송-광주승정간	콘크리트케도	점검용역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이복영	간원강 김경기 문은석	점	0220	(0.3m이하 : 목책)		천문도상방리		재로방리	
											0420	(0.3m초과 0.5m이하 : 광책)		영상		철근노출	
											0620	(0.5m초과 1.0m이하 : 목책)		박리, 박라, 파손		누수수온부	
											1020	(1.0m이상 : 통책)		변대		시공이음판리, 종판리	