


호남고속선 부산고가 _ 72(22.163~22.170km, S13-4)



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.3 m		56				
2	균열	0.1 mm	0.3 m		57				
3	균열	0.1 mm	0.3 m		58				
4	방수균열	6.9 m	0.3 m		59				
5	방수균열	1 m	0.2 m		60				
6	방수균열	0.5 m	0.4 m		61				
7	균열	0.1 mm	0.4 m		62				
8	균열	0.1 mm	0.4 m		63				
9	균열	0.1 mm	0.4 m		64				
10	균열	0.1 mm	0.4 m		65				
11	균열	0.1 mm	0.3 m		66				
12	균열	0.1 mm	0.3 m		67				
13					68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행 사	영 역	영 역	영역	사	과목		단						
						개	인		장	아				
						제	원	지	본	아	별	관	영	지
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검용역	(주) 하국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 부 영	간 원 강 김 경 기 문 원 작 기	영역		0.220	(0.3mm이하 : 흑색)		한목도상판리		재료판리	
								0.420	(0.3mm초과 0.5mm이하 : 황색)		양상		철판노출	
								0.620	(0.5mm초과 1.0mm미만 : 적색)		박리, 박락, 파손		누수, 슬럼프	
								1.020	(1.0mm이상 : 분홍색)		백태		시공이음판리, 종판리	
								1.020	(1.0mm이상 : 분홍색)		백태		시공이음판리, 종판리	