

호남고속선 여천터널 - 토공노반 - 55(42.850~42.860km, L=10m)

42K850

42K860

[illegible]

아
0호

(하)

12주

(속보)

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1	mm	0.5	m	56			
2	균열	0.2	mm	0.4	m	57			
3	균열	0.2	mm	0.8	m	58			
4	균열	0.1	mm	0.5	m	59			
5	균열	0.2	mm	0.4	m	60			
6	균열	0.2	mm	0.8	m	61			
7	균열	0.1	mm	0.5	m	62			
8	균열	0.2	mm	0.4	m	63			
9	균열	0.2	mm	0.5	m	64			
10	균열	0.2	mm	0.7	m	65			
11	균열	0.2	mm	0.4	m	66			
12	균열	0.2	mm	0.5	m	67			
13	균열	0.2	mm	0.4	m	68			
14	균열	0.2	mm	0.8	m	69			
15	균열	0.2	mm	0.5	m	70			
16	균열	0.2	mm	0.5	m	71			
17	균열	0.2	mm	0.4	m	72			
18	균열	0.2	mm	0.8	m	73			
19	균열	0.2	mm	0.5	m	74			
20	균열	0.2	mm	0.3	m	75			
21	균열	0.2	mm	0.8	m	76			
22	균열	0.2	mm	0.4	m	77			
23	균열	0.2	mm	0.4	m	78			
24	균열	0.2	mm	0.5	m	79			
25	균열	0.2	mm	0.4	m	80			
26	균열	0.2	mm	0.8	m	81			
27	균열	0.2	mm	0.4	m	82			
28	균열	0.2	mm	0.5	m	83			
29	균열	0.2	mm	0.4	m	84			
30	균열	0.2	mm	0.5	m	85			
31	균열	0.2	mm	0.8	m	86			
32	균열	0.2	mm	0.5	m	87			
33	균열	0.2	mm	0.5	m	88			
34	균열	0.2	mm	0.8	m	89			
35	균열	0.1	mm	0.6	m	90			
36	균열	0.1	mm	0.6	m	91			
37	균열	0.1	mm	0.6	m	92			
38	균열	0.1	mm	0.6	m	93			
39	균열	0.1	mm	0.6	m	94			
40	균열	0.1	mm	0.6	m	95			
41	균열	0.1	mm	0.6	m	96			
42	균열	0.1	mm	0.6	m	97			
43	균열	0.1	mm	0.6	m	98			
44	균열	0.1	mm	0.6	m	99			
45	균열	0.1	mm	0.6	m	100			
46	균열	0.1	mm	0.6	m	101			
47	균열	0.1	mm	0.3	m	102			
48	균열	0.1	mm	0.3	m	103			
49	균열	0.1	mm	0.3	m	104			
50	균열	0.1	mm	0.3	m	105			
51	균열	0.1	mm	0.3	m	106			
52	균열	0.1	mm	0.3	m	107			
53	균열	0.1	mm	0.3	m	108			
54	균열	0.1	mm	0.4	m	109			
55					110				

시	행 사	용 역 명	용 역 사	구 입 장		단				
				과 목 명	장 소					
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승강간 콘크리트케도 점검용역 (주) 한국구조물안전연구원 (주) 한국국토안전연구원 (제) 한국건설품질연구원	이 박 영	관 원 강 김 경 기 윤 석 기	영원	 0220 (0.3mm이하 : 흑색)	천문도상판리		제로발리	
						 0420 (0.3mm초과 0.5mm이하 : 청색)	양산		철근노출	
						 0620 (0.5mm초과 1.0mm미만 : 적색)	바리, 바리, 파손		누수습윤부	
						 1020 (1.0mm이상 : 분홍색)	백티		시공이음판리, 종판리	