


호남고속선 호암교-95(46.977~46.984km, S19-4)

46K977

46K984
19 SPAN - 4




가 (하위)

(아호)



HSB상단



12주 0차

$$\begin{pmatrix} 0 & 1 \\ 1 & 0 \end{pmatrix}$$

연번	산상	폭	연장	비고	연번	산상	폭	연장	비고
1	균열	0.1 mm	0.3 m		56				
2	균열	0.1 mm	0.3 m		57				
3	균열	0.1 mm	0.3 m		58				
4	균열	0.1 mm	0.3 m		59				
5	경계부 균열	0.3 mm	0.3 m		60				
6	균열	0.1 mm	0.3 m		61				
7	경계부 균열	0.3 mm	0.3 m		62				
8	균열	0.1 mm	0.3 m		63				
9	균열	0.1 mm	0.3 m		64				
10	균열	0.1 mm	0.4 m		65				
11	균열	0.1 mm	0.4 m		66				
12	균열	0.1 mm	0.4 m		67				
13	경계부 균열	0.3 mm	0.3 m		68				
14	균열	0.1 mm	0.4 m		69				
15	방수균열	0.8 m	0.4 m		70				
16	방수균열	0.5 m	0.3 m		71				
17	방수균열(신장)	0.4 m	0.2 m		72				
18	균열	0.1 mm	0.7 m		73				
19	균열	0.1 mm	0.7 m		74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				