


호남고속선 호암교-132(47.236~47.243km, S27-1)

P26

47K243

47K236

27 SPAN - 1



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.3 m		56				
2	균열	0.1 mm	0.3 m		57				
3	균열	0.1 mm	0.3 m		58				
4	균열	0.1 mm	0.7 m		59				
5	균열	0.1 mm	0.6 m		60				
6	균열	0.1 mm	0.6 m		61				
7	균열	0.1 mm	0.8 m		62				
8	균열	0.1 mm	0.8 m		63				
9					64				
10					65				
11					66				
12					67				
13					68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행 사	영 역	영 역	영 역	사	인		구 간		
						개 설	적 입 지		장	아
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 편크리트케도 정경영역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 박 영	간 완 강 김 경 기 윤 석 기	영역		0.220 (0.3m이하 : 폭식)	참목도상본린	
								0.420 (0.3m초과 0.5m이하 : 형식)	양상	
								0.620 (0.5m초과 1.0m이하 : 적식)	바닥,벽면,파손	
								1.020 (1.0m이상 : 분통식)	백태	
								0.820	시공이음본린,종본린	