


한남고속선 한암교 - 토랑노반 32(47.790~47.800km, L=10.0m)



연번	순차	특	연장	비고	연번	순차	특	연장	비고
1	균열 0.1	0.7 mm			56	균열 0.2	0.2 mm	0.5 m	
2	균열 0.1	mm 0.8 m			57	균열 0.1	mm 0.4 m		
3	균열 0.1	mm 0.5 m			58	균열 0.1	mm 0.8 m		
4	균열 0.1	mm 0.8 m			59	균열 0.2	mm 0.5 m		
5	균열 0.1	mm 0.5 m			60	균열 0.1	mm 0.4 m		
6	균열 0.1	mm 0.8 m			61	균열 0.1	mm 0.8 m		
7	균열 0.2	mm 0.4 m			62	균열 0.2	mm 0.5 m		
8	균열 0.2	mm 0.8 m			63	균열 0.1	mm 0.4 m		
9	균열 0.1	mm 0.5 m			64	균열 0.1	mm 0.4 m		
10	균열 0.1	mm 0.5 m			65	균열 0.1	mm 0.4 m		
11	균열 0.1	mm 0.4 m			66	균열 0.1	mm 0.4 m		
12	균열 0.1	mm 0.5 m			67	균열 0.3	mm 0.5 m	신규	
13	균열 0.1	mm 0.8 m			68	균열 0.3	mm 0.5 m	신규	
14	균열 0.2	mm 0.4 m			69	균열 0.3	mm 0.5 m	신규	
15	균열 0.2	mm 0.5 m			70	균열 0.3	mm 0.5 m	신규	
16	균열 0.2	mm 0.5 m			71	균열 0.3	mm 0.5 m	신규	
17	균열 0.2	mm 0.5 m			72	균열 0.3	mm 0.5 m	신규	
18	균열 0.1	mm 0.4 m			73	균열 0.3	mm 0.5 m	신규	
19	균열 0.1	mm 0.8 m			74	균열 0.3	mm 0.5 m	신규	
20	균열 0.1	mm 0.5 m			75				
21	균열 0.2	mm 0.4 m			76				
22	균열 0.1	mm 0.8 m			77				
23	균열 0.2	mm 0.5 m			78				
24	균열 0.1	mm 0.4 m			79				
25	균열 0.2	mm 0.5 m			80				
26	균열 0.1	mm 0.4 m			81				
27	균열 0.1	mm 0.8 m			82				
28	균열 0.1	mm 0.4 m			83				
29	균열 0.2	mm 0.5 m			84				
30	균열 0.1	mm 0.8 m			85				
31	균열 0.1	mm 0.5 m			86				
32	균열 0.2	mm 0.4 m			87				
33	균열 0.1	mm 0.5 m			88				
34	균열 0.1	mm 0.4 m			89				
35	균열 0.2	mm 0.5 m			90				
36	균열 0.1	mm 0.4 m			91				
37	균열 0.1	mm 0.5 m			92				
38	균열 0.1	mm 0.4 m			93				
39	균열 0.1	mm 0.8 m			94				
40	균열 0.2	mm 0.5 m			95				
41	균열 0.1	mm 0.4 m			96				
42	균열 0.1	mm 0.5 m			97				
43	균열 0.1	mm 0.5 m			98				
44	균열 0.1	mm 0.4 m			99				
45	균열 0.1	mm 0.8 m			100				
46	균열 0.2	mm 0.5 m			101				
47	균열 0.1	mm 0.4 m			102				
48	균열 0.1	mm 0.8 m			103				
49	균열 0.2	mm 0.5 m			104				
50	균열 0.1	mm 0.4 m			105				
51	균열 0.2	mm 0.5 m			106				
52	균열 0.1	mm 0.4 m			107				
53	균열 0.2	mm 0.5 m			108				
54	균열 0.1	mm 0.4 m			109				
55	균열 0.1	mm 0.8 m			110				