


호남고속선장구표-123(49.349~49.356km, S25-2)

49K349

49K356
25 SPAN -2



연번	손상	폭	연장	비고	연번	손상	폭	연장	비고
1	강제부 균열	0.3 mm	0.3 m		55				
2	강제부 균열	0.3 mm	0.3 m		56				
3	균열	0.1 mm	0.4 m		57				
4	균열	0.1 mm	0.4 m		58				
5	강제부 균열	0.3 mm	0.3 m		59				
6	균열	0.1 mm	0.3 m		60				
7	강제부 균열	0.3 mm	0.3 m		61				
8	균열	0.1 mm	0.3 m		62				
9	균열	0.1 mm	0.4 m		63				
10	균열	0.1 mm	0.4 m		64				
11	균열	0.2 mm	0.4 m		65				
12	균열	0.1 mm	0.4 m		66				
13	균열	0.2 mm	0.4 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.2 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18	균열	0.2 mm	0.3 m		72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행사	영역	영역	영역	사	이부영		구분			
					과일전입지	정보이별책입지				
KORAIL KOREA RAILROAD 한국철도공사	2017년도 호남고속선 오송-광주승경간 콘크리트캐드 점검공역	(주) 한국구조물안전연구원 (주) 한국국토안전연구원 (재) 한국건설품질연구원	이부영	김윤강 김경기 문석기	영원		0220 (0.3m이하 : 철책)		차료분리	
							0420 (0.3m초과 0.5m이하 : 형식)		양상	
							0620 (0.5m초과 1.0m이하 : 직식)		박리, 박락, 파손	
							1020 (1.0m이상 : 불용식)		번대	
									누수, 침윤부	
									사이클음 분리, 총 분리	