


호남고속선장구표_179(49.741~49.748km, S36-3)



연번	연경				비고
	손상	폭	연경	비고	
1	균열	0.1 mm	0.3 m	55	
2	균열	0.1 mm	0.3 m	56	
3	균열	0.1 mm	0.3 m	57	
4	강재부 균열	0.3 mm	0.55 m	58	
5	강재부 균열	0.3 mm	0.55 m	59	
6	균열	0.3 mm	0.3 m	60	
7	강재부 균열	0.1 mm	0.3 m	61	
8	강재부 균열	0.3 mm	0.3 m	62	
9	균열	0.1 mm	0.4 m	63	
10	균열	0.1 mm	0.4 m	64	
11	균열	0.1 mm	0.6 m	65	
12	균열	0.1 mm	0.5 m	66	
13	균열	0.1 mm	0.3 m	67	
14	균열	0.1 mm	0.1 m	68	
15	균열	0.1 mm	0.3 m	69	
16	균열	0.1 mm	0.4 m	70	
17	균열	0.1 mm	0.4 m	71	
18				72	
19				73	
20				74	
21				75	
22				76	
23				77	
24				78	
25				79	
26				80	
27				81	
28				82	
29				83	
30				84	
31				85	
32				86	
33				87	
34				88	
35				89	
36				90	
37				91	
38				92	
39				93	
40				94	
41				95	
42				96	
43				97	
44				98	
45				99	
46				100	
47				101	
48				102	
49				103	
50				104	
51				105	
52				106	
53				107	
54				108	

[illegible]