



호남고속선 장구교_211(49.965~49.972km, S42-5)


P42
49K972

49K972

49K965


$$\begin{pmatrix} \frac{a}{b} \\ 0 \end{pmatrix}$$
$$\left(\frac{a}{0^a} \right)$$


PCL 상용



2차 (주요)

(속)
음향)

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.3 m		55				
2	균열	0.1 mm	0.75 m		56				
3	균열	0.1 mm	0.6 m		57				
4	균열	0.1 mm	0.3 m		58				
5	균열	0.1 mm	0.7 m		59				
6	강재부 균열	0.3 mm	0.3 m		60				
7	균열	0.1 mm	0.7 m		61				
8	균열	0.1 mm	0.3 m		62				
9	균열	0.1 mm	0.7 m		63				
10	강재부 균열	0.3 mm	0.3 m		64				
11	균열	0.1 mm	0.7 m		65				
12	강재부 균열	0.3 mm	0.3 m		66				
13	균열	0.1 mm	0.7 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.1 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18	균열	0.1 mm	0.5 m		72				
19	균열	0.1 mm	0.3 m		73				
20	강재부 균열	0.2 mm	0.5 m		74				
21	균열	0.1 mm	0.8 m		75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]