


4(54.304~54.314km, L=10m)

[illegible]

시행사	영역	영역	영역	사	장		단
					개설 책임자	분야별 책임자	
KORAIL KOREA RAILROAD 한국철도공사	2017년도 호남고속선 오송~광주승정간 콘크리트케도 점검공역	(주) 한국구조물안전연구원 (주) 한국국토안전연구원 (재) 한국건설품질연구원	이 박 영	김 원 강 김 경 기 윤 석 기	영	 0.22.0 (0.3m이하 : 흑색)	점목도상판리
						 0.42.0 (0.3m초과 0.5m이하 : 청색)	망상
						 0.62.0 (0.5m초과 1.0m미만 : 적색)	박리·박락·표손
						 1.02.0 (1.0m이상 : 분홍색)	백태
						 0.22.0 (0.3m이하 : 흑색)	재료판리
						 0.42.0 (0.3m초과 0.5m이하 : 청색)	철근노출
 0.62.0 (0.5m초과 1.0m미만 : 적색)	부수, 슬럼프						
 1.02.0 (1.0m이상 : 분홍색)	콘크리트 침투, 종판리						