


호남고속선 정지고가_264(58.732~58.739km, S49-2)



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.1 mm	0.4 m			55				
2	균열 0.1 mm	1.2 m			56				
3	균열 0.1 mm	0.4 m			57				
4	균열 0.1 mm	0.7 m			58				
5	균열 0.1 mm	0.4 m			59				
6	균열 0.1 mm	0.4 m			60				
7	균열 0.1 mm	0.7 m			61				
8	균열 0.1 mm	0.4 m			62				
9	균열 0.1 mm	0.4 m			63				
10	균열 0.1 mm	0.4 m			64				
11	균열 0.1 mm	0.4 m			65				
12	균열 0.1 mm	0.4 m			66				
13	균열 0.1 mm	0.4 m			67				
14	균열 0.1 mm	0.4 m			68				
15	균열 0.1 mm	0.7 m			69				
16	균열 0.1 mm	0.7 m			70				
17	균열 0.1 mm	0.5 m			71				
18	균열 0.1 mm	0.5 m			72				
19	균열 0.1 mm	0.7 m			73				
20	균열 0.1 mm	0.7 m			74				
21	균열 0.1 mm	0.4 m			75				
22	균열 0.1 mm	0.4 m			76				
23	균열 0.1 mm	0.4 m			77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시	행	사	용	역	영	용	역	사	구			연														
									과	영	자															
KORAIL	한국철도공사	KOREA RAILROAD	2017년도	화물고속선	오송-광주	승정간	콘크리트케도	점검용역	(주) 한국구조물안전연구원	(주) 한국도로안전연구원	이 복 영	간	영	강	경	기	원	서	기	연						
																					이	복	영			
																								간	영	강
〰〰																										