

호남고속선 정지코가_489(60.308~60.316km, S94-2)

60K308

60K316
94 SPAN - 2

94 SPAN - 2

The diagram illustrates a 16QAM signal processing system. It shows two parallel processing paths for TM 265.2 and TM 243.1, each receiving a 16QAM signal from a PCL channel. The paths involve demodulation, channel estimation, and equalization. The TM 265.2 path includes a 16QAM demodulator, a channel estimator, and a 16QAM equalizer. The TM 243.1 path includes a 16QAM demodulator, a channel estimator, and a 16QAM equalizer. The diagram also shows the PCL channel and the 16QAM signal processing blocks.

연번	산상	북	연장	비고	연번	산상	북	연장	비고
1	군열	0.2 mm	0.3 m		55				
2	군열	0.1 mm	0.4 m		56				
3	군열	0.1 mm	0.3 m		57				
4	경계부 군열	0.2 mm	0.5 m		58				
5	경계부 군열	0.2 mm	0.5 m		59				
6	군열	0.1 mm	0.7 m		60				
7	군열	0.1 mm	0.4 m		61				
8	군열	0.1 mm	0.4 m		62				
9	군열	0.1 mm	0.4 m		63				
10	군열	0.1 mm	0.4 m		64				
11	군열	0.1 mm	0.4 m		65				
12	군열	0.1 mm	0.4 m		66				
13	군열	0.1 mm	0.4 m		67				
14	군열	0.1 mm	0.4 m		68				
15	군열	0.1 mm	0.4 m		69				
16	군열	0.1 mm	0.4 m		70				
17	군열	0.1 mm	0.4 m		71				
18	군열	0.1 mm	0.4 m		72				
19	군열	0.1 mm	0.4 m		73				
20	군열	0.1 mm	0.4 m		74				
21	군열	0.1 mm	0.4 m		75				
22	군열	0.1 mm	0.4 m		76				
23	군열	0.1 mm	0.4 m		77				
24	군열	0.1 mm	0.4 m		78				
25	군열	0.1 mm	0.4 m		79				
26	군열	0.1 mm	0.4 m		80				
27	군열	0.1 mm	0.4 m		81				
28	군열	0.1 mm	0.4 m		82				
29	군열	0.1 mm	0.4 m		83				
30	군열	0.1 mm	0.4 m		84				
31	군열	0.1 mm	0.4 m		85				
32	군열	0.1 mm	0.4 m		86				
33	군열	0.1 mm	0.4 m		87				
34	군열	0.1 mm	0.4 m		88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행사	영역명	주요사업내용	(주)한국조물안전연구원 (주)한국도로안전연구원 (재)한국건설품질연구원	이력영역	간접경리평가원천성기	종류	0.220 (0.3mm이하 : 흑색)	한목도장본리		재료본리	
							0.420 (0.3mm초과 0.5mm이하 : 청색)	망상		철근노출	
							0.620 (0.5mm초과 1.0mm이하 : 적색)	바리,벽박,파손		누수,습윤부	
							1.020 (1.0mm이상 : 분홍색)	변태		시공이음본리,충돌본리	