


호남고속선 정지코가_652(61.457~61.464km, S124-6)

61K464

61K457

124 SPAN - 6



원본	손상	폭	연장	비고	원본	손상	폭	연장	비고
1	경계부 균열	0.2 mm	0.3 m		55				
2	경계부 균열	0.2 mm	0.3 m		56				
3	균열	0.1 mm	0.4 m		57				
4	경계부 균열	0.2 mm	0.8 m		58				
5	균열	0.2 mm	0.8 m		59				
6	균열	0.2 mm	0.6 m		60				
7	균열	0.2 mm	0.6 m		61				
8	균열	0.2 mm	0.8 m		62				
9	균열	0.1 mm	0.4 m		63				
10	균열	0.2 mm	0.6 m		64				
11	균열	0.2 mm	0.3 m		65				
12	균열	0.1 mm	0.4 m		66				
13	균열	0.1 mm	0.4 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.2 mm	1.0 m		69				
16	균열	0.1 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]