


호남고속선 정지고가\_679(61.644~61.651km, S128-1)

61K651

61K644

128 SPAN - 1

[illegible]

|                                                                                                                                                                                                                                                               |                                               |   |               |   |   |   |   |   |   |   |   |   |   |   |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|---|---------------|---|---|---|---|---|---|---|---|---|---|---|
| <div>한국철도공사<br/>KOREA RAILROAD</div>                                                                                                                                         | 시                                             | 행 | 사             | 공 | 역 | 명 | 공 | 역 | 사 | 이 | 복 | 영 | 구 | 분 |
|                                                                                                                                                                                                                                                               | 과 임 부 임 자                                     |   | 장 의 이 별 명 임 자 |   |   |   |   |   |   |   |   |   |   |   |
|                                                                                                                                                                                                                                                               | 2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검용역             |   |               |   |   |   |   |   |   |   |   |   |   |   |
|                                                                                                                                                                                                                                                               | (주)한국구조물안전연구원<br>(주)한국토목안전연구원<br>(재)한국건설품질연구원 |   |               |   |   |   |   |   |   |   |   |   |   |   |
|                                                                                                                                                                                                                                                               | 김운강<br>김경기<br>윤석기                             |   |               |   |   |   |   |   |   |   |   |   |   |   |
| 일반                                                                                                                                                                                                                                                            |                                               |   |               |   |   |   |   |   |   |   |   |   |   |   |
| <div><div></div><div>0.220 (0.3m이하 : 흑색)</div><div>원무도상본리</div><div></div></div>            |                                               |   |               |   |   |   |   |   |   |   |   |   |   |   |
| <div><div></div><div>0.420 (0.3m초과 0.5m이하 : 황색)</div><div>양산</div><div></div></div>         |                                               |   |               |   |   |   |   |   |   |   |   |   |   |   |
| <div><div></div><div>0.620 (0.5m초과 1.0m이하 : 적색)</div><div>바다, 바다, 파손</div><div></div></div> |                                               |   |               |   |   |   |   |   |   |   |   |   |   |   |
| <div><div></div><div>1.020 (1.0m이상 : 분홍색)</div><div>백태</div><div></div></div>               |                                               |   |               |   |   |   |   |   |   |   |   |   |   |   |
| <div><div></div><div>0.020</div><div>지층이음본리,층본리</div><div></div></div>                      |                                               |   |               |   |   |   |   |   |   |   |   |   |   |   |