


와 남극권 39(70.970~70.980km, L=10m)



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.2	mm 0.4	m		55	균열	0.2 mm 0.4	m	
2	균열 0.2	mm 0.5	m		56	균열	0.2 mm 0.8	m	
3	균열 0.2	mm 0.8	m		57	균열	0.2 mm 0.4	m	
4	균열 0.2	mm 0.5	m		58	균열 0.4	mm 1.2	m	
5	균열 0.2	mm 0.8	m		59	균열	0.2 mm 0.4	m	
6	균열 0.2	mm 0.5	m		60	균열 0.2	mm 0.4	m	
7	균열 0.2	mm 0.5	m		61	균열	0.2 mm 0.4	m	
8	균열 0.2	mm 0.5	m		62	층분리	1.0 mm 10.0	m	
9	균열 0.2	mm 0.8	m		63	균열	0.3 mm 1.0	m	신규
10	균열 0.2	mm 0.4	m		64	경계부 균열	0.3 mm 1.0	m	신규
11	경계부 균열	0.3 mm 0.8	m		65				
12	균열	0.2 mm 0.5	m		66				
13	균열	0.2 mm 0.4	m		67				
14	경계부 균열	0.3 mm 0.8	m		68				
15	균열	0.2 mm 0.5	m		69				
16	균열	0.2 mm 0.8	m		70				
17	균열	0.2 mm 0.4	m		71				
18	균열	0.2 mm 0.8	m		72				
19	균열	0.2 mm 0.4	m		73				
20	균열	0.2 mm 0.5	m		74				
21	균열	0.2 mm 0.8	m		75				
22	균열	0.2 mm 0.8	m		76				
23	균열	0.2 mm 0.8	m		77				
24	균열	0.2 mm 0.5	m		78				
25	균열	0.2 mm 0.4	m		79				
26	균열	0.2 mm 0.8	m		80				
27	균열	0.2 mm 0.4	m		81				
28	균열	0.2 mm 0.8	m		82				
29	균열	0.2 mm 0.8	m		83				
30	균열	0.2 mm 0.4	m		84				
31	균열	0.2 mm 0.8	m		85				
32	균열	0.2 mm 0.8	m		86				
33	균열	0.2 mm 0.4	m		87				
34	균열	0.2 mm 0.4	m		88				
35	균열	0.2 mm 0.4	m		89				
36	균열	0.2 mm 0.8	m		90				
37	균열	0.2 mm 0.5	m		91				
38	균열	0.2 mm 0.4	m		92				
39	경계부 균열	0.3 mm 0.3	m		93				
40	균열	0.2 mm 0.5	m		94				
41	균열	0.2 mm 0.8	m		95				
42	균열	0.2 mm 0.4	m		96				
43	균열	0.2 mm 0.8	m		97				
44	균열	0.2 mm 0.4	m		98				
45	균열	0.2 mm 0.8	m		99				
46	균열	0.2 mm 0.4	m		100				
47	균열	0.2 mm 0.8	m		101				
48	균열	0.2 mm 0.4	m		102				
49	균열	0.2 mm 0.8	m		103				
50	균열	0.2 mm 0.8	m		104				
51	균열	0.2 mm 0.4	m		105				
52	균열	0.2 mm 0.5	m		106				
53	균열	0.2 mm 0.4	m		107				
54	균열	0.2 mm 0.8	m		108				

[illegible]