


호남고속선 죽산교_118(73.924~73.931km, S24-2)

73K924

73K931
24 SPAN - 2



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	경계부 균열 0.2 mm	0.3 m			55				
2	균열 0.2 mm	0.4 m			56				
3	균열 0.2 mm	0.4 m			57				
4	경계부 균열 0.2 mm	0.3 m			58				
5	경계부 균열 0.2 mm	0.3 m			59				
6	균열 0.1 mm	0.4 m			60				
7	균열 0.1 mm	0.4 m			61				
8	균열 0.1 mm	0.4 m			62				
9	균열 0.1 mm	0.4 m			63				
10	균열 0.1 mm	0.4 m			64				
11	균열 0.1 mm	0.4 m			65				
12	균열 0.1 mm	0.4 m			66				
13	균열 0.1 mm	0.4 m			67				
14	균열 0.1 mm	0.4 m			68				
15	균열 0.2 mm	1.2 m			69				
16	균열 0.2 mm	0.7 m			70				
17	균열 0.1 mm	0.4 m			71				
18	균열 0.1 mm	0.4 m			72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				



한국철도공사
KOREA RAILROAD