


호남고속선 죽산교_335(75.381~75.388km, S67-4)


75K388

75K381



$$\left(\begin{array}{c} \text{아} \\ \text{하} \\ \text{오} \\ \text{포} \end{array} \right)$$

(아
아)

PCL상면



12월 09일

$$\left(\begin{array}{c} \text{유형} \\ \text{이론} \end{array} \right)$$


연번	순차	폭	연장	비고	연번	순차	폭	연장	비고
1	균열	0.1	mm	0.4	m	55			
2	균열	0.1	mm	0.4	m	56			
3	균열	0.2	mm	0.65	m	57			
4	강계부 균열	0.3	mm	0.8	m	58			
5	균열	0.1	mm	0.7	m	59			
6	균열	0.1	mm	0.65	m	60			
7	균열	0.1	mm	0.7	m	61			
8	균열	0.2	mm	0.65	m	62			
9	균열	0.2	mm	0.7	m	63			
10	균열	0.1	mm	0.3	m	64			
11	균열	0.2	mm	0.65	m	65			
12	균열	0.2	mm	0.65	m	66			
13	균열	0.2	mm	0.65	m	67			
14	균열	0.1	mm	0.7	m	68			
15	균열	0.1	mm	0.4	m	69			
16	균열	0.2	mm	0.65	m	70			
17	균열	0.2	mm	0.7	m	71			
18	균열	0.1	mm	0.3	m	72			
19	균열	0.1	mm	0.4	m	73			
20	균열	0.2	mm	0.65	m	74			
21	균열	0.2	mm	0.65	m	75			
22	균열	0.2	mm	0.65	m	76			
23	균열	0.1	mm	0.3	m	77			
24	균열	0.1	mm	0.4	m	78			
25	균열	0.2	mm	1.0	m	79			
26	망상 균열	1.0	mm	7.0	m	80			
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]