

호남고속선 중리코-10 (75.762~75.769km, S2-4)

75K762	75K769	2 SPAN- 4
POL상면 TCL측면 TCL상면 TM.280.3	POL상면 TCL측면 TCL상면 TM.277.1	POL상면 TCL측면 TCL상면 TM.271.4
1 2 3 4 5 6 7 8 9 10 11	1 2 3 4 5 6 7 8 9 10 11	1 2 3 4 5 6 7 8 9 10 11
15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.7 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4	15.0.1/0.7 15.0.1/0.7 15.0.1/0.7 15.0.1/0.7 15.0.1/0.7 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4	15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.7 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4 15.0.1/0.4
TM.280.3 TM.277.1 TM.271.4	TM.280.3 TM.277.1 TM.271.4	TM.280.3 TM.277.1 TM.271.4
POL상면 TCL측면 TCL상면 TM.280.3	POL상면 TCL측면 TCL상면 TM.277.1	POL상면 TCL측면 TCL상면 TM.271.4

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.7 m		55				
2	균열	0.1 mm	0.7 m		56				
3	강재부 균열	0.3 mm	0.4 m		57				
4	균열	0.1 mm	0.4 m		58				
5	균열	0.1 mm	0.4 m		59				
6	균열	0.1 mm	0.7 m		60				
7	균열	0.1 mm	0.4 m		61				
8	균열	0.1 mm	0.7 m		62				
9	균열	0.1 mm	0.7 m		63				
10	균열	0.1 mm	0.7 m		64				
11	균열	0.1 mm	0.4 m		65				
12	균열	0.1 mm	0.7 m		66				
13	균열	0.1 mm	0.4 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.1 mm	0.7 m		70				
17	균열	0.1 mm	0.4 m		71				
18	균열	0.1 mm	0.7 m		72				
19	균열	0.1 mm	0.7 m		73				
20	균열	0.1 mm	0.4 m		74				
21	균열	0.1 mm	0.7 m		75				
22	균열	0.1 mm	0.7 m		76				
23	균열	0.1 mm	0.3 m		77				
24	균열	0.2 mm	0.4 m		78				
25	균열	0.2 mm	0.4 m		79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]