

호남고속선 중리교_118 (76.504~76.511km, S24-2)

Technical drawing of a 24-span bridge deck, showing cross-sections 76K504 and 76K511. The drawing includes labels for PCL, TOL, and TM sections, and a detailed cross-section of the bridge deck with numbered spans and dimensions.

Labels and Dimensions:

- PCL상면** (PCL Top View)
- TOL상면** (TOL Top View)
- TM 236.2**
- TM 279.4**
- TM 294.1**
- TM 093.2**
- 76K504**
- 76K511**
- 24 SPAN - 1**

Span Details:

- Span 1:** Dimensions: 16.0, 1/0.6
- Span 2:** Dimensions: 16.0, 1/0.4
- Span 3:** Dimensions: 16.0, 1/0.4
- Span 4:** Dimensions: 16.0, 1/0.4
- Span 5:** Dimensions: 16.0, 1/0.4
- Span 6:** Dimensions: 16.0, 1/0.4
- Span 7:** Dimensions: 16.0, 1/0.4
- Span 8:** Dimensions: 16.0, 1/0.4
- Span 9:** Dimensions: 16.0, 1/0.4
- Span 10:** Dimensions: 16.0, 1/0.4
- Span 11:** Dimensions: 16.0, 1/0.4

Section Details:

- Section 1:** Dimensions: 16.0, 1/0.4
- Section 2:** Dimensions: 16.0, 1/0.4
- Section 3:** Dimensions: 16.0, 1/0.4
- Section 4:** Dimensions: 16.0, 1/0.4
- Section 5:** Dimensions: 16.0, 1/0.4
- Section 6:** Dimensions: 16.0, 1/0.4
- Section 7:** Dimensions: 16.0, 1/0.4
- Section 8:** Dimensions: 16.0, 1/0.4
- Section 9:** Dimensions: 16.0, 1/0.4
- Section 10:** Dimensions: 16.0, 1/0.4
- Section 11:** Dimensions: 16.0, 1/0.4

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	강제부 균열	0.3	mm	0.3	m	55			
2	강제부 균열	0.3	mm	0.3	m	56			
3	강제부 균열	0.3	mm	0.3	m	57			
4	균열	0.1	mm	0.4	m	58			
5	강제부 균열	0.3	mm	0.3	m	59			
6	열상균열	0.3	m	7	m	60			
7	열상균열	0.3	m	1.8	m	61			
8	균열	0.1	mm	0.6	m	62			
9	균열	0.1	mm	0.4	m	63			
10	균열	0.1	mm	0.4	m	64			
11	균열	0.1	mm	0.4	m	65			
12	균열	0.1	mm	0.3	m	66			
13	균열	0.1	mm	0.4	m	67			
14	균열	0.2	mm	0.5	m	68			
15	균열	0.2	mm	0.4	m	69			
16	균열	0.1	mm	0.4	m	70			
17	균열	0.1	mm	0.4	m	71			
18	균열	0.1	mm	0.4	m	72			
19	균열	0.1	mm	0.4	m	73			
20	균열	0.1	mm	0.4	m	74			
21	균열	0.1	mm	0.4	m	75			
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행	사명	종업원명	종업원사	종업원		종업원
				종업원명	종업원사	
한국철도공사 KOREA RAILROAD	홍남고속선 오송-광주승강간 콘크리트케도 점검용역	(주) 한국구조물안전연구원 (주) 한국콘크리트안전연구원 (재) 한국건설품질연구원	이복영	강문기 윤성기	0220 (0.3mm이하 : 황색) 0420 (0.3mm초과 ~ 0.5mm이하 : 녹색) 0620 (0.5mm초과 ~ 1.0mm이하 : 적색) 1020 (1.0mm초과 : 분홍색)	점검대상관리 양정 불수출물 배리(배락) 파손 배타 오염 시공이음관리(측면관리)