

2017년도 호남고속선 오송-광주송정간 콘크리트 궤도 점검용역

- 외관조사망도 -


2017. 11.

U23_성덕제2터널(153k113~153k223, L=110m)
G77_성덕제2터널_토공노반(153k223~153k333, L=110m)


21. U23_성덕제2터널

점검 일자	2017. 07.12~2017. 10.25
평균 기온	15.5 ~ 24.5℃


외관조사망도 번호
U23성덕제2터널_1(153.113~153.124km, L=11m)




외관조사망도 번호
U23성덕제2터널_2(153.124~153.135km, L=11m)




외관조사망도 번호
U23성덕제2터널_3(153.135~153.146km, L=11m)




외관조사망도 번호
U23성덕제2터널_4(153.146~153.157km, L=11m)




외관조사망도 번호
U23성덕제2터널_5(153.157~153.168km, L=11m)




외관조사망도 번호
U23성덕제2터널_6(153.168~153.179km, L=11m)




외관조사망도 번호
U23성덕제2터널_7(153.179~153.190km, L=11m)



외관조사망도 번호
U23성덕제2터널_8(153.190~153.201km, L=11m)



외관조사망도 번호
U23성덕제2터널_9(153.201~153.212km, L=11m)



외관조사망도 번호
U23점덕제2터널_10(153.212~153.223km, L=11m)

