


22. G77_성덕제2터널_토공노반

점검 일자	2017. 07.12~2017. 10.25
평균 기온	15.5 ~ 24.5℃


호남고속선 성덕제2터널_토공노반_1(153.223~153.236km, L=13m)

외관조사망도 번호


G77_성덕제2터널_토공노반_1(153.223~153.236km, L=13m)

[illegible]


외관조사망도 번호
G77_성덕제2터널_토공노반_2(153.236~153.245km, L=9m)



외관조사망도 번호
G77_성덕제2터널_토공노반_3(153.245~153.255km, L=10m)




외관조사망도 번호
G77_성덕제2터널_토공노반_4(153.255~153.264km, L=9m)



호남고속선 성덕제2터널_토공노반_5(153.264~153.274km, L=10m)

외관조사망도 번호


G77_성덕제2터널_토공노반_5(153.264~153.274km, L=10m)

[illegible]

호남고속선 성덕제2터널_토공노반_6(153.274~153.283km, L=9m)

외관조사망도 번호


G77_성덕제2터널_토공노반_6(153.274~153.283km, L=9m)

[illegible]

호남고속선 성덕제2터널_토공노반_7(153.283~153.293km, L=10m)

외관조사망도 번호


G77_성덕제2터널_토공노반_7(153.283~153.293km, L=10m)

[illegible]

호남고속선 성덕제2터널_토공노반_8(153.293~153.302km, L=9m)

외관조사망도 번호


G77_성덕제2터널_토공노반_8(153.293~153.302km, L=9m)

[illegible]

호남고속선 성덕제2터널_토공노반_9(153.302~153.311km, L=9m)

외관조사망도 번호


G77_성덕제2터널_토공노반_9(153.302~153.311km, L=9m)

[illegible]

호남고속선 성덕제2터널_토공노반_10(153.311~153.320km, L=9m)

외관조사망도 번호


G77_성덕제2터널_토공노반_10(153.311~153.320km, L=9m)

[illegible]

호남고속선 성덕제2터널_토공노반_11(153.320~153.328km, L=8m)

외관조사망도 번호


G77_성덕제2터널_토공노반_11(153.320~153.328km, L=8m)

[illegible]

호남고속선 성덕제2터널_토공노반_12(153.328~153.333km, L=5m)

외관조사망도 번호

G77_성덕제2터널_토공노반_12(153.328~153.333km, L=5m)

[illegible]