

2017년도 호남고속선 오송-광주송정간 콘크리트 궤도 점검용역

- 외관조사망도 -


2017. 11.

B56_서삼천교(159k657~159k817, L=160m)
G83_서삼천교_토공노반(159k817~159k863, L=46m)


33. B56_서삼천교

점검 일자	2017. 07.12~2017. 10.25
평균 기온	15.5 ~ 24.5℃


외관조사망도 번호
B56_호남고속선 서삼천교_1(1 SPAN -1)




외관조사망도 번호
B56_호남고속선 서삼천교_2(1 SPAN -2)




외관조사망도 번호
B56_호남고속선 서삼천교_3(1 SPAN -3)




외관조사망도 번호
B56_호남고속선 서삼천교_4(1 SPAN -4)




외관조사망도 번호
B56_호남고속선 서삼천교_5(1 SPAN -5)




외관조사망도 번호
B56_호남고속선 서삼천교_6(2 SPAN-1)




외관조사망도 번호
B56_호남고속선 서삼천교_7(2 SPAN -2)




외관조사망도 번호
B56_호남고속선 서삼천교_8(2 SPAN -3)




외관조사망도 번호
B56_호남고속선 서삼천교_9(2 SPAN -4)




B56_호남고속선 서삼천교_10(2 SPAN -5)




외관조사망도 번호
B56_호남고속선 서삼천교_11(3 SPAN -1)




외관조사망도 번호
B56_호남고속선 서삼천교_12(3 SPAN -2)




외관조사망도 번호
B56_호남고속선 서삼천교_13(3 SPAN -3)




외관조사망도 번호
B56_호남고속선 서삼천교_14(3 SPAN -4)




외관조사망도 번호
B56_호남고속선 서삼천교_15(3 SPAN -5)




외관조사망도 번호
B56_호남고속선 서삼천교_16(4 SPAN -1)




외관조사망도 번호
B56_호남고속선 서삼천교_17(4 SPAN -2)



외관조사망도 번호
B56_호남고속선 서삼천교_18(4 SPAN -3)



외관조사망도 번호
B56_호남고속선 서삼천교_19(4 SPAN -4)



외관조사망도 번호
B56_호남고속선 서삼천교_20(4 SPAN -5)

