

2017년도 호남고속선 오송-광주송정간 콘크리트 궤도 점검용역

- 외관조사망도 -


2017. 11.

B62_마령제1고가(169k698~169k858, L=160m)
G93_마령제1고가_토공노반(169k858~170k179, L=321m)


53. B62_마령제1고가

점검 일자	2017. 07.12~2017. 10.25
평균 기온	11.8 ~ 21.6℃


외관조사망도 번호
B58_호남고속선 마령제1고가_1(1 SPAN -1)




외관조사망도 번호
B58_호남고속선 마령제1고가_2(1 SPAN -2)




외관조사망도 번호
B58_호남고속선 마령제1고가_3(1 SPAN -3)




외관조사망도 번호
B58_호남고속선 마령제1고가_4(1 SPAN -4)




외관조사망도 번호
B58_호남고속선 마령제1고가_5(1 SPAN -5)




외관조사망도 번호
B58_호남고속선 마령제1고가_6(2 SPAN -1)




외관조사망도 번호
B58_호남고속선 마령제1고가_7(2 SPAN -2)




외관조사망도 번호
B58_호남고속선 마령제1고가_8(2 SPAN -3)




외관조사망도 번호
B58_호남고속선 마령제1고가_9(2 SPAN -4)




외관조사망도 번호
B58_호남고속선 마령제1고가_10(2 SPAN -5)




외관조사망도 번호
B58_호남고속선 마령제1고가_11(3 SPAN -1)




B58_호남고속선 마령제1고가_12(3 SPAN -2)




외관조사망도 번호
B58_호남고속선 마령제1고가_13(3 SPAN -3)




외관조사망도 번호
B58_호남고속선 마령제1고가_14(3 SPAN -4)




외관조사망도 번호
B58_호남고속선 마령제1고가_15(3 SPAN -5)




외관조사망도 번호
B58_호남고속선 마령제1고가_16(4 SPAN -1)




외관조사망도 번호
B58_호남고속선 마령제1고가_17(4 SPAN -2)



외관조사망도 번호
B58_호남고속선 마령제1고가_18(4 SPAN -3)



외관조사망도 번호
B58_호남고속선 마령제1고가_19(4 SPAN -4)



외관조사망도 번호
B58_호남고속선 마령제1고가_20(4 SPAN -5)

