







■ 장압교

▣ 정적데이터




1. Load Case 1






2. Load Case 2






3. Load Case 3






4. Load Case 4






5. Load Case 5






6. Load Case 6




7 Load Case 7




8 Load Case 8



9 Load Case 9




10. Load Case 10




동적데이터


1) 10km




DT1




DT2




DT3



DT4




DT5




DT6


2) 20km




DT1




DT2




DT3



DT4




DT5




DT6


3) 30km




DT1




DT2




DT3



DT4




DT5




DT6


4) 40km




DT1




DT2




DT3



DT4




DT5




DT6


5) 50km




DT1




DT2




DT3



DT4




DT5




DT6


6) 65km




DT1




DT2




DT3



DT4




DT5




DT6


■ 교유진동수




10km/hr - ACC1




10km/hr - ACC2




20km/hr - ACC1




20km/hr - ACC2




30km/hr - ACC1




30km/hr - ACC2




40km/hr - ACC1




40km/hr - ACC2




50km/hr - ACC1



50km/hr - ACC2



65km/hr - ACC1



65km/hr - ACC2

■ 시험차량 계량증명서

계 량 증 명 서 (제 출 용1) 전표번호 : 0010			계 량 증 명 서 (제 출 용2) 전표번호 : 0009		
일 자	2016-05-11		일 자	2016-05-11	
차 량 번 호	세종06가5298		차 량 번 호	충남06노6315	
거 래 처	안전공사		거 래 처	안전공사	
행 선 지			행 선 지		
제 품	골재		제 품	골재	
총 중 량	10:57	27,630 kg	총 중 량	10:52	27,050 kg
공 차 중 량	10:55	0 kg	공 차 중 량	10:52	0 kg
감 량	0 %	0 kg	감 량	0 %	0 kg
실 중 량	27,630 kg		실 중 량	27,050 kg	
단 가	0 원	0 원	단 가	0 원	0 원
웅진계량소 공주시 금흥동 528-1번지 (고철,비철,파지,기타지류,공장철거) 041-854-1993 010-4727-8993 ※ 본 증명서는 재발행하지 않음. ※ 필히 재확인해 주십시오. ※ 계량후 중량의 변동은 본사에서 책임지지 않음. ※ 상기와 같이 제품 계량을 증명함.			웅진계량소 공주시 금흥동 528-1번지 (고철,비철,파지,기타지류,공장철거) 041-854-1993 010-4727-8993 ※ 본 증명서는 재발행하지 않음. ※ 필히 재확인해 주십시오. ※ 계량후 중량의 변동은 본사에서 책임지지 않음. ※ 상기와 같이 제품 계량을 증명함.		
1호차 - 총중량(276.3kN))			2호차 - 총중량(270.5kN))		